

**Appendix A - Remedial Action List (2017) for Group Water Schemes**

Local Authority	EPA Scheme Code	Group Water Scheme	Source Type	Source of Supply	Existing Treatment Process	Reason for Inclusion on Remedial Action List.
Cavan	0200PRI0219	Crossdowney	SU	Lough Atrain.	Clarification, rapid gravity filtration, active filtration & disinfection (chlorination).	Failure to meet DWR standards for chemical & indicator parameters.
Cavan	0200PRI0290	Drumkeery	SU	Drumkeery Lough	Clarification, dissolved air flotation, active filtration, pH correction & disinfection (chlorination).	Failure to meet DWR standards for chemical & indicator parameters.
Cavan	0200PRI0267	Milltown	Mixed	Borehole & Lough Derrybrick	Filtration (pressure) & disinfection (chlorination).	Failure to meet DWR standards for chemical & indicator parameters.
Clare	0300PRI2000	Beechwood Lawn/ Bodyke	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Clare	0300PRI2011	Kilnaboy (AKA Killianaboy)	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Clare	0300PRI2006	Ranaghan	GR	Borehole	Filtration (simple particle) & disinfection (chlorination & UV).	Inadequate treatment.
Cork	0500PRI1714	Ballinguyroe/ Tankardstown	GR	Spring	Disinfection (chlorination).	Inadequate treatment.
Cork	0500PRI1704	Caherdrinny	GR	Borehole	Disinfection (chlorination & UV).	Failure to meet DWR standards for indicator parameters.
Cork	0500PRI1707	Downing	GR	Borehole	pH correction & disinfection (chlorination).	Failure to meet DWR standards for microbiological & indicator parameters.
Donegal	0600PRI3073	Tory Island	SU	Lough Ahooey	Filtration (slow sand), UV (on raw water) & disinfection (chlorination).	Failure to meet DWR standards for microbiological & indicator parameters.
Donegal	0600PRI3099	Townawilly	SU	Lough Ameencheen	Filtration (pressure), pH correction, membrane filtration (5 micron), aeration/ventilation & disinfection (chlorination & UV).	Failure to meet DWR standards for chemical & indicator parameters.
Galway	1200PRI0104	Anbally & District	GR	Borehole	Disinfection (chlorination & UV).	Inadequate treatment.
Galway	1200PRI0756	Ballymanagh (Craughwell)	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Galway	1200PRI0145	Balroebuckbeg	GR	Borehole	Disinfection (chlorination & UV).	Inadequate treatment.
Galway	1200PRI0151	Belclare	GR	Borehole	Disinfection (chlorination & UV).	Failure to meet DWR standards for microbiological & indicator parameters.
Galway	1200PRI0152	Belmont (Kilconly)	GR	Borehole	Disinfection (chlorination & UV).	Failure to meet DWR standards for microbiological & indicator parameters.
Galway	1200PRI1081	Boyounagh/ Ballyedmond - Gortaganny	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Galway	1200PRI0177	Caherlea/ Gurrane	GR	Borehole	Disinfection (chlorination).	Failure to meet DWR standards for microbiological & indicator parameters.
Galway	1200PRI0179	Cahermorris, Corrandulla	GR	Borehole	Disinfection (chlorination & UV).	Inadequate treatment.
Galway	1200PRI0175	Carhereenlea (Athenny)	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Galway	1200PRI0195	Carramore-Knock	SU	Lough Corrib	Disinfection (UV).	Failure to meet DWR standards for microbiological & indicator parameters.
Galway	1200PRI0216	Claren/ Knocklehard	SU	Lough Corrib	Filtration & disinfection (chlorination & UV).	Failure to meet DWR standards for chemical parameters.
Galway	1200PRI0217	Claretuam	GR	Borehole	Disinfection (chlorination).	Failure to meet DWR standards for microbiological & indicator parameters.
Galway	1200PRI0236	Cloonkeen/ Toomard	GR	Borewell	Disinfection (chlorination).	Inadequate treatment.
Galway	1200PRI0238	Cloonluane (Renvyle)	SU	Tully Lough	Filtration (pressure), ozonisation, pH correction & disinfection (chlorination & UV).	Failure to meet DWR standards for chemical parameters.
Galway	1200PRI0286	Clough/ Cummer	GR	Borehole	Disinfection (chlorination & UV).	Inadequate treatment.
Galway	1200PRI0248	Cluide/ Cahermorris	GR	Borehole	None.	No treatment.
Galway	1200PRI0261	Coole	GR	Borehole	Disinfection (chlorination & UV).	Inadequate treatment.
Galway	1200PRI0445	Corohan (Milltown North East)	GR	Borehole	Disinfection (chlorination & UV).	Inadequate treatment.
Galway	1200PRI0312	Esker/ Eyrecourt	GR	Borehole	Disinfection (chlorination & UV).	Inadequate treatment.
Galway	1200PRI0318	Feigh East & West	GR	Borehole	Disinfection (UV).	Inadequate treatment.
Galway	1200PRI0371	Killasmuggaun	SU	Spring	Disinfection (chlorination).	Failure to meet DWR standards for microbiological & indicator parameters.
Galway	1200PRI0411	Lettergesh/ Mullaghgloss	SU	Mountain Stream	Filtration (pressure), pH correction, active filtration & disinfection (chlorination & UV).	Failure to meet DWR standards for chemical parameters.
Galway	1200PRI0415	Lisananey/ Liskeavy	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Galway	1200PRI0914	Looscaun	GR	Borehole	Disinfection (chlorination & UV).	Inadequate treatment.
Galway	1200PRI0496	Roo	GR	Borehole	None.	No treatment.
Galway	1200PRI0503	Rusheens	GR	Borehole	Disinfection (chlorination & UV).	Inadequate treatment.
Galway	1200PRI0507	Seehan (Gort)	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Galway	1200PRI0526	Tierneevin	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Galway	1200PRI0585	Tubber	GR	Borehole	Disinfection (chlorination & UV).	Failure to meet DWR standards for microbiological & indicator parameters.
Kerry	1300PRI3061	An Ghraig	GR	Borehole	Iron & manganese removal & disinfection (UV).	Failure to meet DWR standards for indicator parameters.

**Appendix A - Remedial Action List (2017) for Group Water Schemes**

Local Authority	EPA Scheme Code	Group Water Scheme	Source Type	Source of Supply	Existing Treatment Process	Reason for Inclusion on Remedial Action List.
Kerry	1300PRI2022	Bonane	SU	Upland stream	Disinfection (chlorination).	Failure to meet DWR standards for microbiological, chemical & indicator parameters.
Kerry	1300PRI3012	Cappanalea	GR	Borehole	Filtration (simple particle), pH correction & disinfection (chlorination).	Failure to meet DWR standards for microbiological, chemical & indicator parameters.
Kerry	1300PRI2065	Kells	SU	Two small upland streams	Disinfection (chlorination).	Failure to meet DWR standards for microbiological & indicator parameters.
Kildare	1400PRI3031	Ballindoolin	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Kildare	1400PRI3032	Ballyroe/ Leinster Lodge	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Kildare	1400PRI3055	Kilteel	GR	Well	Disinfection (chlorination).	Inadequate treatment.
Kilkenny	1500PRI3006	Balief/ Clomantagh	GR	Borehole at Balief	Disinfection (chlorination).	Inadequate treatment.
Kilkenny	1500PRI3165	Barna/ Kilrush	GR	Borehole at Barna	Disinfection (chlorination).	Failure to meet DWR standards for microbiological & indicator parameters.
Laois	1600PRI4000	Ballymaddock	GR	Ballymaddock borehole	Disinfection (UV).	Inadequate treatment.
Laois	1600PRI3001	Cullahill	SP	Tuberbow Spring	Filtration (simple particle) & disinfection (chlorination & UV).	Failure to meet DWR standards for chemical parameters.
Leitrim	1700PRI1202	Cornashamsoge	SU	Mountain stream	Filtration & disinfection (chlorination & UV).	Failure to meet DWR standards for microbiological & indicator parameters.
Limerick	1900PRI3261	Barnagh/ Glendarragh	GR	Groundwater	Filtration (media), pH correction & disinfection (chlorination).	Inadequate treatment.
Limerick	1900PRI3108	Knockainey/ Kilballyowen	GR	Groundwater	Disinfection (chlorination).	Inadequate treatment.
Louth	2100PRI3001	Ballymakenny/ Sandpit	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Louth	2100PRI3005	Drybridge/ Waterunder	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Louth	2100PRI3004	Grangebellew	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Louth	2100PRI3007	Mountain Park	SP	Spring	Disinfection (chlorination).	Inadequate treatment.
Louth	2100PRI3007	Sheepgrange	GR	Borehole	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2003	Attymass	SP	Attymass Shallow Spring	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2011	Barneycarroll	GR	Barneycarroll Well	Disinfection (chlorination).	Failure to meet DWR standards for microbiological & indicator parameters.
Mayo	2200PRI2014	Belderg	SU	Rathnavasteen River	Filtration & disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2020	Brackoon/ Spaddagh	SU	Caheer Lough	Filtration & disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2557	Callow Lake	SU	Callow Lake	Clarification, filtration & disinfection (chlorination & UV).	Failure to meet DWR standards for chemical & indicator parameters.
Mayo	2200PRI2122	Cloonmore/ Cloonlavlis	SP	Cloonmore/ Cloonlavlis Spring	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2339	Cloonlyon	GR	Knock Airport Well	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2037	Creggduff	GR	Creggduff Well	Filtration & disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2035	Curranaboy (Cornboy)	SP	Curraunboy Well	Disinfection (UV).	Inadequate treatment.
Mayo	2200PRI2126	Derryvoghy	GR	Ballyclogher Well	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2047	Drum/ Binghamstown	SP	Drum Spring	Filtration (pressure) & disinfection (chlorination & UV).	Inadequate treatment.
Mayo	2200PRI2128	Drumsheen/ Newtown	SP	Drumsheen/ Newtown Spring	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2130	Errew	SP	Killeen Shallow Spring	Disinfection (UV).	Inadequate treatment.
Mayo	2200PRI2543	Fahy/ Drummindoo	SU	Clogher Lough	Filtration & disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2147	Funshinaugh/ Cross	SU	Lough Corrib	Filtration & disinfection (chlorination & UV).	Inadequate treatment.
Mayo	2200PRI2056	Glencorrib	SU	Lough Corrib	Filtration & disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2065	Johnstown/ Levalleyroe	SP	Levallyroe Spring	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2075	Kilmeena	SU	Ballinlough Lake	Filtration & disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2133	Kilmovree/ Urlaur	SU	Urlaur Lough	Filtration & disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2073	Killaturley	GR	Killaturley Open Well	Disinfection (chlorination & UV).	Inadequate treatment.
Mayo	2200PRI2070	Killgalligan	GR	Killgalligan Mountain Well	None.	No treatment.
Mayo	2200PRI2136	Loughaunnaman/ Ballinamalla	GR	Loughaunnaman Well	Disinfection (chlorination & UV).	Inadequate treatment.
Mayo	2200PRI2668	Lough Carra	SU	Lough Carra	Ozonisation, MMS & disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2083	Lough Mask/ Creevagh	SU	Lough Mask	Ozonisation & disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2150	Midfield	GR	Kilkelly Well	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2549	Nephin Valley	SU	Nephin Stream	Filtration (media), ozonisation & disinfection (chlorination & UV).	Failure to meet DWR standards for chemical & indicator parameters.

**Appendix A - Remedial Action List (2017) for Group Water Schemes**

Local Authority	EPA Scheme Code	Group Water Scheme	Source Type	Source of Supply	Existing Treatment Process	Reason for Inclusion on Remedial Action List.
Mayo	2200PRI2093	Parke	SU	Derryhick	Clarification & disinfection (chlorination & UV).	Failure to meet DWR standards for chemical & indicator parameters.
Mayo	2200PRI2141	Rosmoney	GR	Rosmoney Well	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2324	Rossport	SP	Rossport Spring	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2103	Roy Bingham's	SP	Spring	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2100	Robeen	SU	Lough Carra	Disinfection (chlorination).	Inadequate treatment.
Mayo	2200PRI2105	Sraheen (Foxford)	SU	Lough Conn	Ozonisation & disinfection (chlorination & UV).	Failure to meet DWR standards for indicator parameters.
Mayo	2200PRI2111	Tooreen/ Aghamore	SP	Carn Beg Spring	Disinfection (chlorination & UV).	Failure to meet DWR standards for microbiological & indicator parameters.
Mayo	2200PRI2559	PBKS	SU	Carrowmore Lake	Adsorption clarifier, clarification & disinfection (chlorination & UV)	Failure to meet DWR standards for chemical & indicator parameters.
Offaly	2500PRI2001	Aghancon	SP	Ballycurragh Spring	Disinfection (chlorination & UV).	Inadequate treatment.
Offaly	2500PRI2012	Clonfanlough	GR	Clonfanlough Borehole	Disinfection (UV).	Inadequate treatment.
Offaly	2500PRI2016	Killeigh/ Meelaghans	SP	Toberfin Spring	Disinfection (chlorination).	Inadequate treatment.
Offaly	2500PRI2007	Boher	SP	Springs at Castlearmstrong & Bellair	Disinfection (chlorination).	Inadequate treatment.
Offaly	2500PRI2017	Mountlucas	GR	Riverlyons Borehole	Disinfection (chlorination & UV).	Failure to meet DWR standards for chemical parameters.
Roscommon	2600PRI3008	Brosna	SP	Spring	Disinfection (chlorination).	Inadequate treatment.
Sligo	2700PRI1027	Carrownadargney	GR	Well	None.	No treatment.
Sligo	2700PRI1034	Keash	SU	Lough Labe.	Filtration (pressure), active filtration & disinfection (chlorination & UV).	Failure to meet DWR standards for chemical parameters.
Waterford	3100PRI3015	Ballydurn	GR	Borehole	Disinfection (UV).	Inadequate treatment.
Waterford	3100PRI3041	Momminane	SP	Spring	Disinfection (chlorination & UV).	Failure to meet DWR standards for microbiological & indicator parameters.
Wicklow	3400PRI1111	Blakestown/ Brittonstown	SP	Spring	Iron & manganese removal & disinfection (chlorination & UV).	Failure to meet DWR standards for microbiological & indicator parameters.
Wicklow	3400PRI1112	Cornagower Park Residents	GR	Borehole	Iron & manganese removal, turbidity filtration & disinfection (chlorination).	Failure to meet DWR standards for indicator parameters.
Wicklow	3400PRI1301	Johnstown (Hollywood)	GR	Spring	None.	No treatment.